



WMK-F4 BOM list			
Item	Part Name	Qty	Remark
1	Base	1	Image -1
2	Base support	2	Image -1
3	Stand support bracket	1	Image -1
4	Wall mount	1	Image -1
5	Pen holder	1	Image -1
6	Left Lock Plate	1	Image -1
7	Right Lock Plate	1	Image -1
8	PC table	1	Image -1
9	Screw M4*8mm, P Head, Black	2	•
10	Screw M8*15mm, B Head, Black	12	0-
11	Washer M8, Black	12	0
12	Washer ID=7mm OD=19mm H=1mm	4	0
13	Screw M10*25mm, Six - angled screw, Black	4	Camana
14	Screw M3*6mm Flat Head, Black	3	
15	Screw M6*12, hexagonal screw	2	
16	Lobe knobs screw M6*16L	2	-




#### Step 1.

Lock the brakes of the castors before doing any assembly for safety purposes.






Step 3. Place the base support bracket on top of the base supports and fix in place with 2 screws (M4\*6mm, P Head, Black).




Step 4.

Attach the wall mount to the base supports then fix it in place with six-angled screw (M10\*25mm, Black) + washer (ID=7mm,OD=19mm,H=1mm).




#### Step 5.

- 1. Attach the PC table to the base supports, then fix it in place with n2 Lobe screw nobs M6\*16L\*2pcs. (Image 2, 2-1)
- 2. Place Left & Right Lock Plate on base supports, then fix it with 2 screws M6\*12, hexagonal screw. (Image 3, 3-1)



#### Step 6.

Both sides of the upright supports support have screw holes for pen holder which can can be fixed to either side by the user. Use 3 screws (M3\*6mm, Flat Head, Black). (Image 4.)



#### Step 7. PC table

Pull up the left and right lock plate. Flip up the PC tray and fix with the locking plate (Image 5,5-1,5-2), (Image 6).

